

Attachment 12  
 Reporting Form - Construction Activities  
 Village of Castleton-on-Hudson

Property Owner	Address	Inspection By	Dates	Comments	Action
Richard Nunziato	11 Park Way	Clark Engineering & Surveying, P.C./Doug Clark, Derrick Gardner	2004	Slope & erosion control issues for new construction of residence.	Erosion control measures established, foundation drains installed, silt fence, haybales, seed & mulch.
1 Benedict Street	1 Benedict Street	Clark Engineering & Surveying, P.C./Doug Clark, Derrick Gardner	7/31/06, 2/30/07	Fill material being placed at top of slopedrains outlet on slope. Tree Clearing on slope.	Drains rerouted. Brush removed from embankment, stumps left in place. Silt fence & seeding.
Daniel O'Neill	77 Scott Avenue	Clark Engineering & Surveying, P.C./Derrick Gardner	9/14/06, 1/27/07	Brush & debris causing erosion, sedimentation of catch basin.	Brush & debris removed from slope. Slope regraded. Silt fence, seed and mulch installed.
Donald Walsh	9 Hillview Terrace	Clark Engineering & Surveying, P.C./Doug Clark, Derrick Gardner	2005/2007	Tree clearing along steep slope requested in front of planning board.	Plan submitted and initial approval. No construction started yet.
KSR Holding, LLC	Seaman Avenue	Clark Engineering & Surveying, P.C./Doug Clark, Derrick Gardner	2006/2007	8-Lot subdivision review.	Stormwater plan approved by planning board with review by Clark Engineering & Surveying, P.C.
Village of Castleton-on-Hudson	Scott Avenue	Clark Engineering & Surveying, P.C./Derrick Gardner, Kyle Gardner	2006/2007	Sidewalk, curbing, shoulder, & catch basin replacement along portion of Scott Avenue.	Silt fence, haybales, seed & mulch implemented. Full time inspection by Clark Engineering & Surveying, P.C.
Resurrection Nursing Home	Route 9J	Clark Engineering & Surveying, P.C./Derrick Gardner	2/2/2007	Fill material and grading taking place.	Less than 1/2 acre of disturbance, no erosion issues, no further action.
Schodack Central School	Scott Avenue	Clark Engineering & Surveying, P.C./Doug Clark, Derrick Gardner	2007/2008	Elementary school improvements. Stormwater control plans set up.	SWPP reviewed and some inspection of work completed.
Doug Porter	29 Prins Hill Way	Clark Engineering & Surveying, P.C./Derrick Gardner	4/23/08, 6/5/08, 10/22/08	Tree clearing & disturbance along steep slope. Erosion control concerns.	Stop work ordered. Plan submitted by owner to planning board. Plantings & erosion control measures implemented.
Joseph Scandura	110 Green Avenue	Clark Engineering & Surveying, P.C./Derrick Gardner	2008	Initial submission of subdivision plans.	Recommendations made for site plan submission. No further action by owner.
Village of Castleton-on-Hudson	Green Avenue & 2nd Street	Clark Engineering & Surveying, P.C./Derrick Gardner, Kyle Gardner	2008/2009	Road reconstruction, including: water, stormwater, sidewalks, curbing, & pavement.	Silt fence, haybales, seed & mulch implemented. Full time inspection by Clark Engineering & Surveying, P.C.